

**APPENIX A**

<b>Site</b>	<b>Street Address</b>	<b>Latitude</b>	<b>Longitude</b>	<b>Pole Type</b>
NE-NY-PLNDMANR-00001	<b>74 Ivy Way</b>	40.8221	-73.695145	Replacement Wood Pole
NE-NY-PLNDMANR-00002	<b>1 Murray Ave</b>	40.82565	-73.701016	Replacement Wood Pole
NE-NY-PLNDMANR-00003	<b>36 Murray Ave</b>	40.82567	-73.697897	Replacement Wood Pole
NE-NY-PLNDMANR-00004	<b>4 North</b>	40.82579	-73.703833	Replacement Wood Pole
NE-NY-PLNDMANR-00005	<b>71 Davis Rd</b>	40.8237	-73.697207	Replacement Wood Pole
NE-NY-PLNDMANR-00006	<b>11 Hunting Rd</b>	40.82373	-73.699197	Replacement Wood Pole
NE-NY-PLNDMANR-00007	<b>29 N Plandome Rd</b>	40.82303	-73.701607	Replacement Wood Pole
NE-NY-PLNDMANR-00008	<b>122 Huting Rd</b>	40.82207	-73.699786	Replacement Wood Pole
NE-NY-PLNDMANR-00009	<b>15 Beachway</b>	40.82184	-73.704454	Replacement Wood Pole
NE-NY-PLNDMANR-00010	<b>1 Terrace Dr.</b>	40.82071	-73.701921	Replacement Wood Pole
NE-NY-PLNDMANR-00011	<b>12 Ockland Dr.</b>	40.81994	-73.695676	Replacement Wood Pole
NE-NY-PLNDMANR-00012	<b>1 Leeds Dr</b>	40.82084	-73.69769	Replacement Wood Pole
NE-NY-PLNDMANR-00013	<b>36 Amherst Rd</b>	40.82012	-73.693755	Replacement Wood Pole
NE-NY-PLNDMANR-00014	<b>59 Richards Rd</b>	40.82275	-73.696358	Existing Wood Pole
NE-NY-PLNDMANR-00017	<b>17 Leeds Drive</b>	40.81817	-73.696513	New Wood Pole
NE-NY-PLNDMANR-00058	<b>21 Capi Jct.</b>	40.82363	-73.703844	Replacement Wood Pole